

VCDS-Lite Version: Release 1.2

Wednesday, 09 March 2022, 12:49:27:0

Chassis Type: 8Z - Audi A2

Scan: 01,02,03,08,15,16,17,18,37,45,46,56,57,75,76,77

Address 01: Engine Labels: 036-906-034-APE.LBL

Controller: 036 906 034 Q

Component: MARELLI 4LV 3720

Coding: 00051

Shop #: WSC 02138

VCID: 20336383B3DB

WAUZZZ8ZZ1N051799 AUZ7Z0A1835314

7 Faults Found:

17559 - Long Term Fuel Trim Additive Air; Bank 1; Range 1: System too Lean

P1151 - 35-00 - -

17584 - Bank1: O2 (Lambda) Correction Behind Catalyst: Control Limit Reached

P1176 - 35-10 - - - Intermittent

18057 - Powertrain Data Bus: Missing Message from ABS Controller

P1649 - 35-10 - - - Intermittent

17589 - Linear O2 Sensor; Reference Voltage: Open Circuit

P1181 - 35-10 - - - Intermittent

17604 - Oxygen (Lambda) Sensor Heater Circuit: B1 S1: Electrical Malfunction

P1196 - 35-10 - - - Intermittent

17586 - Linear O2 Sensor; Pump Current: Open Circuit

P1178 - 35-10 - - - Intermittent

16522 - Oxygen (Lambda) Sensor B1 S2: Signal too High

P0138 - 35-10 - - - Intermittent

Readiness: 0010 0001

Address 03: ABS Brakes Labels: None

Controller: 8Z0 907 379 B

Component: ESP 20 CAN V015

Coding: 10758

Shop #: WSC 00000

VCID: 47E1D81F76B5

2 Faults Found:

65535 - Internal Control Module Memory Error

00-00 - -

00778 - Steering Angle Sensor (G85)

49-00 - No Communications

Address 08: Auto HVAC Labels: None

Controller: 8Z2 820 043

Component: A2-KLIMAVOLLAUTOMAT 0406

VCID: F59DE2D7DCD9

1 Fault Found:

00710 - Defroster Flap Positioning Motor (V107)

41-10 - Blocked or No Voltage - Intermittent

Address 15: Airbags Labels: 8Z0-959-655.LBL

Controller: 8Z0 959 655 E

Component: Airbag Front+Seite 5005

Coding: 00102

Shop #: WSC 02152

VCID: 4EEFED3B99CF

No fault code found.

Address 17: Instruments Labels: 8Z0-920-xxx-17.LBL

Controller: 8Z0 920 950 A

Component: W1-KOMBIINSTR. VDO D13

Coding: 05442

Shop #: WSC 00258

VCID: 3C0BB7F33F73

WAUZZZ8ZZ1N051799 AUZ7Z0A1835314

2 Faults Found:

01320 - Control Module for Climatronic (J255)

49-10 - No Communications - Intermittent

01336 - Data Bus for Comfort System

80-10 - Single-Wire Operation - Intermittent

Address 45: Inter. Monitor Labels: 8E0-951-177.LBL

Controller: 8Z0 951 177

Component: Innenraumueberw. D04

Coding: 00001

Shop #: WSC 00000

VCID: 55DD0257BC19

1 Fault Found:

01463 - Alarm triggered by Sensor for anti-theft alarm System

43-00 - Closed

Address 46: Central Conv. Labels: None

Controller: 8Z0 959 433 F

Component: Komfortgerät T1D 03B3

Coding: 06858

Shop #: WSC 02138

VCID: 49E5DE2760A1

10 Faults Found:

01370 - Alarm triggered by Interior Monitoring

35-00 - -

01369 - Alarm triggered by Hood Switch

35-00 - -

01371 - Alarm triggered by Door Contact Switch; Driver's Side

35-00 - -

01572 - Alarm triggered by Door Contact Switch; Passenger Side

35-00 - -

01561 - Left Rear Door

59-10 - Can't Unlock - Intermittent

01561 - Left Rear Door

61-10 - Won't De-Safe - Intermittent

01562 - Right Rear Door

59-10 - Can't Unlock - Intermittent

01562 - Right Rear Door

61-10 - Won't De-Safe - Intermittent

01559 - Drivers Door

61-00 - Won't De-Safe

01560 - Passenger Door

61-00 - Won't De-Safe

Address 56: Radio Labels: 8D0-035-1xx-56.LBL

Controller: 4B0 035 152 B

Component: Radio 0001

Coding: 00501

Shop #: WSC 02138

VCID: 18434B636B8B

1 Fault Found:

00852 - Loudspeaker(s); Front

36-10 - Open Circuit - Intermittent

End -----