

VCDS-Lite  
Windows Based VAG/VAS Emulator  
Version: Release 1.2  
www.Ross-Tech.com

Workshop Code: 000 00000

Self-Diagnosis Log  
Saturday, 16 January 2021, 16:46:06:39307

VIN Number: WAUZZZ8Z83N025060 License Plate: VU03SKJ  
Mileage: 159447 Repair Order:

Chassis Type: 8Z - Audi A2  
Scan: 01,02,03,08,15,16,17,18,37,45,46,56,57,75,76,77

---

Address 01: Engine Labels: 045-906-019-AMF.LBL  
Controller: 045 906 019 G  
Component: 1,4l R3 EDC G000SG 1514  
Coding: 00005  
Shop #: WSC 02138  
VCID: 1945D7EC9081  
WAUZZZ8Z83N025060 AUZ7Z0B2289207

2 Faults Found:

19463 - Camshaft Position Sensor (G40): No Signal  
P3007 - 35-10 - - - Intermittent  
18062 - Please check DTC Memory of Instrument Cluster  
P1654 - 35-00 - -

Readiness: N/A

---

Address 03: ABS Brakes Labels: None  
Controller: 8Z0 907 379 D  
Component: ESP FRONT MK60 0101  
Coding: 0007303  
Shop #: WSC 02154  
VCID: 49E547AC60A1

No fault code found.

---

VCDS-Lite  
Self-Diagnosis Log  
Saturday, 16 January 2021, 16:46:06:39307  
Page 2

VIN Number: WAUZZZ8Z83N025060 License Plate: VU03SKJ

Address 08: Auto HVAC Labels: None

Controller: 8Z0 820 043 F

Component: A2-KLIMAVOLLAUTOMAT 0514

VCID: 3905376C3041

6 Faults Found:

01272 - Positioning Motor for Central Flap (V70)

41-10 - Blocked or No Voltage - Intermittent

00716 - Air recirculation Flap Positioning Motor (V113)

41-10 - Blocked or No Voltage - Intermittent

00727 - Potentiometer in Positioning Motor for Defrost Flap (G135)

30-10 - Open or Short to Plus - Intermittent

00601 - Potentiometer On Positioning Motor for Central Flap (G112)

30-10 - Open or Short to Plus - Intermittent

00819 - High Pressure Sensor (G65)

29-10 - Short to Ground - Intermittent

01273 - Fresh Air Blower (V2)

17-10 - Control Difference - Intermittent

-----  
Address 15: Airbags Labels: 8Z0-959-655.LBL

Controller: 8Z0 959 655 E

Component: Airbag Front+Seite 5005

Coding: 00102

Shop #: WSC 02152

VCID: 4EEF74B099CF

No fault code found.

-----  
Address 17: Instruments Labels: 8Z0-920-xxx-17.LBL

Controller: 8Z0 920 980 Q

Component: KOMBI+WEGFAHRS. VDO D04

Coding: 08430

Shop #: WSC 10001

VCID: 4FD169B49EC5

WAUZZZ8Z83N025060 AUZ7Z0B2289207

2 Faults Found:

01309 - Power Steering Control Module (J500)

49-10 - No Communications - Intermittent

00562 - Sensor for Oil Level/Temperature (G266)

30-10 - Open or Short to Plus - Intermittent

VCDS-Lite  
Self-Diagnosis Log  
Saturday, 16 January 2021, 16:46:06:39307  
Page 3

VIN Number: WAUZZZ8Z83N025060 License Plate: VU03SKJ

Address 45: Inter. Monitor Labels: 8E0-951-177.LBL

Controller: 8Z0 951 177

Component: Innenraumueberw. D04

Coding: 00001

Shop #: WSC 00000

VCID: 55DD9BDCBC19

1 Fault Found:

01463 - Alarm triggered by Sensor for anti-theft alarm System

43-00 - Closed

-----  
Address 46: Central Conv. Labels: None

Controller: 8Z0 959 433 AF

Component: Komfortgerät TBD 1210

Coding: 06831

Shop #: WSC 00590

VCID: 8A6738A0A527

8 Faults Found:

01320 - Control Module for Climatronic (J255)

49-10 - No Communications - Intermittent

01370 - Alarm triggered by Interior Monitoring

35-00 - -

01371 - Alarm triggered by Door Contact Switch; Driver's Side

35-00 - -

01561 - Left Rear Door

59-10 - Can't Unlock - Intermittent

00955 - Key 1

35-10 - - - Intermittent

00532 - Supply Voltage B+

37-10 - Faulty - Intermittent

01332 - Door Control Module; Passenger Side (J387)

49-10 - No Communications - Intermittent

01560 - Passenger Door

61-10 - Won't De-Safe - Intermittent

-----  
Address 56: Radio Labels: 8E0-035-1xx-56.LBL

Controller: 8Z0 035 195 A

Component: symphony II NP2 0008

Coding: 00201

Shop #: WSC 00000

VCID: 3A0728603547

1 Fault Found:

01336 - Data Bus for Comfort System

49-10 - No Communications - Intermittent

End -----