

VEHICLE DIAGNOSTIC REPORT

Date&Time: 07/04/2023 13:25

Path: Select Vehicle Type\Audi A2 2001>\2002 (2)\Saloon\AUA 1.4 L 4 LV / 55kW\Diagnosis\System Scan\

VIN:

Status Report

Code	Status	Description
Status	DTC Counts	System Name
Pass	0	01-Engine
Pass	0	03-ABS Brakes
Fault	9	08-Auto HVAC
Pass	0	15-Airbags
Pass	0	17-Instruments
Pass	0	25-Immobilizer
Fault	1	45-Inter. Monitor
Fault	9	46-Central Conv.
Fault	1	56-Radio
Fault	9	08-Auto HVAC
DTC Code	DTC Status	DTC Content
00710	Passive/Sporadic	Defroster flap motor -V107-locked or has no voltage supply
01272	Passive/Sporadic	Central flap regulator motor -V70-locked or has no voltage supply
01271	Passive/Sporadic	Temperature regulator door motor -V68-locked or has no voltage supply
00716	Passive/Sporadic	Recirculation flap motor -V113-locked or has no voltage supply
00727	Passive/Sporadic	Potentiometer in positioning motor,for defrost flap -G135-Open circuit/short circuit to B+
00601	Passive/Sporadic	Potentiometer - positioning motor,for central flap -G112-Open circuit/short circuit to B+
00600	Passive/Sporadic	Potentiometer - positioning motor,for temperature flap -G92-Open circuit/short circuit to B+
00735	Passive/Sporadic	Potentiometer in positioning motor,for air recirculation flap -G143-Open circuit/short circuit to B+
01273	Passive/Sporadic	Fresh air blower -V2-Control difference
Fault	1	45-Inter. Monitor
DTC Code	DTC Status	DTC Content
01463	Active/static	Alarm triggered by sensor for anti-theft alarm system-Closed
Fault	9	46-Central Conv.
DTC Code	DTC Status	DTC Content
01134	Active/static	Alarm horn-No communication
01370	Active/static	Alarm triggered by interior monitoring-lost23
01368	Active/static	Alarm triggered by luggage compartment switch-lost23
01369	Active/static	Alarm triggered by bonnet switch-lost23
01371	Active/static	Alarm triggered by door contact switch on driver side-lost23
01572	Active/static	Alarm triggered by door contact switch on passenger side-lost23

01561	Passive/Sporadic	Left rear door-does not unlock
01562	Passive/Sporadic	Right rear door-does not unlock
00955	Passive/Sporadic	Key 1-lost23
Fault	1	56-Radio
DTC Code	DTC Status	DTC Content
01317	Passive/Sporadic	Instrument cluster control module -J285-No communication