

Sunday,27,June,2021,17:43:56:50832
VCDS -- Windows Based VAG/VAS Emulator Running on Windows 10 x64
VCDS Version: 21.3.0.0 (x64)
Data version: 20210226 DS325.0
www.Ross-Tech.com

VIN: WAUZZZ8Z13N026535 License Plate: HJ03XHEV2
Mileage: 139096 Repair Order:

Chassis Type: 8Z (8Z - Audi A2 (2000 > 2005))
Scan: 01 02 03 08 15 16 17 18 37 45 46 56 57 75 76 77

VIN: WAUZZZ8Z13N026535

Address 01: Engine Labels: Redir Fail!
Part No: 036 906 013 F
Component: MED7.5.11 4628
Coding: 00051
Shop #: WSC 31414
VCID: 122004285EA9111B65-515A
WAUZZZ8Z13N026535 AUZ7Z0B2289163

1 Fault Found:
16788 - EGR System
P0404 - 35-00 - Range / Performance
Readiness: 1110 0101

Address 03: ABS Brakes Labels: 8Z0-907-379-MK60.1b1
Part No: 8Z0 907 379 D
Component: ESP FRONT MK60 0101
Coding: 0007183
Shop #: WSC 00000 785 00200
VCID: 4992E344237F92C354-515A

No fault code found.

Address 08: Auto HVAC Labels: None
Part No: 8Z0 820 043 D
Component: A2-KLIMAVOLLAUTOMAT 0514
VCID: 377695BC158B143332-2586

1 Fault Found:
00735 - Potentiometer in Positioning Motor for Air recirculation Flap (G143)
30-10 - Open or Short to Plus - Intermittent

Address 15: Airbags Labels: 8Z0-959-655.lbl
Part No: 8Z0 959 655 E
Component: Airbag Front+Seite 5005
Coding: 00102
Shop #: WSC 02152
VCID: 4E98D0588A11B5FB01-515A

No fault code found.

Address 17: Instruments Labels: 8Z0-920-xxx-17.lbl
Part No: 8Z0 920 980 T
Component: KOMBI+WEGFAHRS. VDO D04
Coding: 04442
Shop #: WSC 00182
VCID: 52A0C4289E29D11B25-515A
WAUZZZ8Z13N026535 AUZ7Z0B2289163

No fault code found.

Address 45: Inter. Monitor Labels: 8E0-951-177.lbl
Part No: 8Z0 951 177
Component: Innenraumueberw. D04
Coding: 00001
Shop #: WSC 00000
VCID: 55AA3F34AFC7C623C0-5178

No fault code found.

Address 46: Central Conv. Labels:. 8Z0-959-433.lbl
Part No: 8Z0 959 433 AF
Component: Komfortgerät TBD 1210
Coding: 06859
Shop #: WSC 02138
VCID: 0A101C4836F9D9DB9D-4B18

Subsystem 1 - Part No: 8Z2959802A
Component: Törsteuer.FS BRM 0003

Subsystem 2 - Part No: 8Z2959801A
Component: Törsteuer.BF BRM 0003

No Faults Found
or DTCs not supported by controller
or a communication error occurred

Address 56: Radio Labels: 8E0-035-1xx-56.lbl

Part No: 8Z0 035 186 F
Component: concert II GRO 0008
Coding: 00001
Shop #: WSC 02138
VCID: 3F86FD9C3DBB2C73FA-4B18

No fault code found.

End----- (Elapsed Time: 03:48)-----