

VEHICLE DIAGNOSTIC REPORT

Date&Time: 07/04/2023 13:27

Path: Select Vehicle Type\Audi A2 2001>\2002 (2)\Saloon\AUA 1.4 L 4 LV / 55kW\Diagnosis\System Scan\Read Codes\

VIN:

Read Codes

Code	Status	Description
00710	Passive/Sporadic	Defroster flap motor -V107-locked or has no voltage supply
01272	Passive/Sporadic	Central flap regulator motor -V70-locked or has no voltage supply
01271	Passive/Sporadic	Temperature regulator door motor -V68-locked or has no voltage supply
00716	Passive/Sporadic	Recirculation flap motor -V113-locked or has no voltage supply
00727	Passive/Sporadic	Potentiometer in positioning motor,for defrost flap -G135-Open circuit/short circuit to B+
00601	Passive/Sporadic	Potentiometer - positioning motor,for central flap -G112-Open circuit/short circuit to B+
00600	Passive/Sporadic	Potentiometer - positioning motor,for temperature flap -G92-Open circuit/short circuit to B+
00735	Passive/Sporadic	Potentiometer in positioning motor,for air recirculation flap -G143-Open circuit/short circuit to B+
01273	Passive/Sporadic	Fresh air blower -V2-Control difference