

VCDS-Lite  
Windows Based VAG/VAS Emulator  
Version: Release 1.2  
www.Ross-Tech.com

Workshop Code: 000 00000

Diagnostic Trouble Code Report  
Saturday, 08 April 2023, 13:47:00:4863

VIN Number:   License Plate:  
Mileage:   Repair Order:

Control Module Part Number: 036 906 013 F  
Component and/or Version: MED7.5.11       4628  
Software Coding: 00051  
Additional Info: WAUZZZ8Z03N026882   AUZ7Z0B2288224

2 Faults Found:

16684 - Random/Multiple Cylinder Misfire Detected  
P0300 - 35-00 - -

16688 - Cylinder 4: Misfire Detected  
P0304 - 35-00 - -

Readiness: 1110 0101