

Saturday,26,June,2021,17:57:28:50832  
VCDS -- Windows Based VAG/VAS Emulator Running on Windows 10 x64  
VCDS Version: 21.3.0.0 (x64)  
Data version: 20210226 DS325.0  
www.Ross-Tech.com

VIN: WAUZZZ8Z13N026535 License Plate: HJ03XHE  
Mileage: 139093 Repair Order:

-----  
-----  
  
Chassis Type: 8Z (8Z - Audi A2 (2000 > 2005))  
Scan: 01 02 03 08 15 16 17 18 37 45 46 56 57 75 76 77

VIN: WAUZZZ8Z13N026535

-----  
Address 01: Engine Labels: Redir Fail!  
Part No: 036 906 013 F  
Component: MED7.5.11 4628  
Coding: 00051  
Shop #: WSC 31414  
VCID: 122004285EA9111B65-513C  
WAUZZZ8Z13N026535 AUZ7Z0B2289163

9 Faults Found:

17439 - Intake Manifold Tuning Valve (N316)  
P1031 - 35-00 - Setpoint Not Reached  
17912 - Intake Air System  
P1504 - 35-10 - Leak Detected - Intermittent  
17573 - Long Term Fuel Trim Additive Air; Bank 1; Range 1  
P1165 - 35-10 - System too Rich - Intermittent  
16684 - Random/Multiple Cylinder Misfire Detected  
P0300 - 35-10 - - Intermittent  
16688 - Cylinder 4  
P0304 - 35-10 - Misfire Detected - Intermittent  
16523 - Oxygen (Lambda) Sensor B1 S2  
P0139 - 35-10 - Response too Slow - Intermittent  
17428 - Fuel Pressure Regulation  
P1020 - 35-10 - Control Range Exceeded - Intermittent  
18043 - Powertrain Data Bus  
P1635 - 35-10 - Missing Message from A/C Controller - Intermittent  
16788 - EGR System  
P0404 - 35-00 - Range / Performance  
Readiness: 1000 0001

-----  
Address 03: ABS Brakes Labels: 8Z0-907-379-MK60.1b1  
Part No: 8Z0 907 379 D  
Component: ESP FRONT MK60 0101

Coding: 0007183  
Shop #: WSC 00000 785 00200  
VCID: 4992E344237F92C354-513C

No fault code found.

-----  
Address 08: Auto HVAC                      Labels: None  
Part No: 8Z0 820 043 D  
Component: A2-KLIMAVOLLAUTOMAT 0514  
VCID: 377695BC158B143332-2586

2 Faults Found:

00735 - Potentiometer in Positioning Motor for Air recirculation Flap (G143)  
30-10 - Open or Short to Plus - Intermittent  
00819 - High Pressure Sensor (G65)  
30-00 - Open or Short to Plus

-----  
Address 15: Airbags                      Labels: 8Z0-959-655.lbl  
Part No: 8Z0 959 655 E  
Component: Airbag Front+Seite 5005  
Coding: 00102  
Shop #: WSC 02152  
VCID: 4E98D0588A11B5FB01-515A

No fault code found.

-----  
Address 17: Instruments                      Labels: 8Z0-920-xxx-17.lbl  
Part No: 8Z0 920 980 T  
Component: KOMBI+WEGFAHRS. VDO D04  
Coding: 04442  
Shop #: WSC 00182  
VCID: 52A0C4289E29D11B25-515A  
WAUZZZ8Z13N026535              AUZ7Z0B2289163

1 Fault Found:

01320 - Control Module for Climatronic (J255)  
49-10 - No Communications - Intermittent

-----  
Address 45: Inter. Monitor                      Labels: 8E0-951-177.lbl  
Part No: 8Z0 951 177  
Component: Innenraumueberw.              D04  
Coding: 00001  
Shop #: WSC 00000  
VCID: 55AA3F34AFC7C623C0-5178

No fault code found.

-----  
Address 46: Central Conv.                      Labels: 8Z0-959-433.lbl  
Part No: 8Z0 959 433 AF

Component: Komfortgerät TBD 1210  
Coding: 06859  
Shop #: WSC 02138  
VCID: 0A101C4836F9D9DB9D-4B18

Subsystem 1 - Part No: 8Z2959802A  
Component: Törsteuer.FS BRM 0003

Subsystem 2 - Part No: 8Z2959801A  
Component: Törsteuer.BF BRM 0003

8 Faults Found:

- 01320 - Control Module for Climatronic (J255)
  - 49-10 - No Communications - Intermittent
- 01134 - Alarm Horn (H12)
  - 29-00 - Short to Ground
- 01561 - Rear left door
  - 59-00 - Can't Unlock
- 01561 - Rear left door
  - 61-00 - Won't De-Safe
- 01562 - Rear right door
  - 59-00 - Can't Unlock
- 01562 - Rear right door
  - 61-00 - Won't De-Safe
- 01366 - Opened Due to Crash Signal
  - 36-10 - Open Circuit - Intermittent
- 01560 - Passenger Door
  - 61-10 - Won't De-Safe - Intermittent

-----  
Address 56: Radio Labels: 8E0-035-1xx-56.lbl  
Part No: 8Z0 035 186 F  
Component: concert II GRO 0008  
Coding: 00001  
Shop #: WSC 02138  
VCID: 3F86FD9C3DBB2C73FA-4B32

3 Faults Found:

- 00852 - Loudspeaker(s); Front
  - 36-10 - Open Circuit - Intermittent
- 00856 - Radio Antenna
  - 36-10 - Open Circuit - Intermittent
- 00858 - Connection; Radio Intermediate Frequency (IF) Output to Antenna Amplifier
  - 36-10 - Open Circuit - Intermittent

End----- (Elapsed Time: 03:44)-----