

Saturday, 23 October 2021, 16:10:41.

Control Module Part Number: 036 906 013 F

Component and/or Version: MED7.5.11 5130

Software Coding: 00051

Work Shop Code: WSC 00000

VCID: 1257394B4D77

Additional Info: WAUZZZ8Z34N005350 AUZ7Z0C2422046

5 Faults Found:

16576 - Fuel Pressure Sensor (G247): Short to Ground

P0192 - 35-00 - -

17912 - Shareware Version. To Decode all DTCs

P1504 - 35-00 - Please Register/Activate

16684 - Shareware Version. To Decode all DTCs

P0300 - 35-00 - Please Register/Activate

16688 - Cylinder 4: Misfire Detected

P0304 - 35-00 - -

16686 - Shareware Version. To Decode all DTCs

P0302 - 35-00 - Please Register/Activate