



Log-HJ03XHE-WAUZZZ8Z13N026535-139004.txt

```
38 -----  
-----  
-----  
39 Address 08: Auto HVAC  
Labels: None  
40 Part No: 8Z0 820 043 D  
41 Component:  
A2-KLIMAVOLLAUTOMAT 0514  
42 VCID: 377695BC158B143332-258C  
43  
44 2 Faults Found:  
45 00735 - Potentiometer in  
Positioning Motor for Air  
recirculation Flap (G143)  
46 30-10 - Open or  
Short to Plus - Intermittent  
47 00819 - High Pressure Sensor  
(G65)  
48 30-00 - Open or  
Short to Plus  
49  
50 -----  
-----  
-----  
51 Address 15: Airbags  
Labels: 8Z0-959-655.1b1  
52 Part No: 8Z0 959 655 E  
53 Component: Airbag Front+Seite
```